

Assure Before You Buy! Protect Yourself from Hidden Risks!

CarAssure.com.au



To know how to read the report, please see the end of report.

2:10 PM



2022 Ford Ranger

VIN# MNACMFF70NW243579 Date/time of Inspection: 17/10/25

State: NSw REG# EWF96M 05 Oct 2025

Vehicle information

Brand: Ford

Year of manufacture: 2022

Transmission:

Odometer Reading: 72,411

Engine capacity:

Model: Ranger Colour: white

Fuel type: Diesel

Body type: Ute

Number of cylinders:

Inspection Report Summary

Under the car

Check points: 25 Gearbox No Notes V Engine Check points: 11 No Notes No Notes

Electricity system 🖏 liquids Check points: 15 6 No Notes V Check points:

> Notes: 1 Break System Notes: 1 Check points: 15

0→0 Rear Axle & Drive **0→0** Sheft Check points: 9 Interior No Notes No Notes Check points: 30

Additional Notes: 1 Check points: 6 No Notes Check points: 11

Exterior Check points: 29 Notes: 3

Notes from Mechanic

Noise heard during drive may originate from tyre tread or bearings — workshop lift recommended for isolation. Tailgate repair needed for proper operation. Lifted setup with oversized tyres affects ride comfort, fuel efficiency, and long-term suspension wear.

This Ford Ranger appears mechanically sound and in good condition overall, with the exception of the non-functional tailgate and expected road noise from the aftermarket setup.

Further workshop testing is suggested to confirm bearing conditions.

Check points: 8

Logbook not found in the car, dealer advise that they will provide it later.



Engine (Check points: 25 Notes: 0		
	OK Note N/A		OK Note N/A
Engine Overhaul	✓	Fuel filter	✓
Front Crankshaft oil seal	✓	Air filter	✓
Rear Crankshaft oil seal	✓	Engine sump	✓
Engine Tune-up	✓	Intake manifold	✓
Engine Mount	\checkmark	Radiator hose	✓
Dil pan gasket	✓	Pulley belt	✓
Valve cover gasket	✓	Engine cover	✓
Oil filter housing o-ring	✓	Coolant reservoir	✓
ntake manifold gasket	✓	Steering pump	✓
Radiator	✓	Windshield washer reservoir	✓
Engine timing cover gasket	✓	Radiator and cap	✓
Water pump	✓	Radiator coolant overflow	✓
Timing belt	✓	Engine bolt disassemble signs	✓
Oil pump gasket Front Crankshaft oil seal Rear Crankshaft oil seal Transmission mount Oil pan gasket	\rightarrow	Oil Cooler Pipe Gear performance Transmission sump Transmission intercooler	\rightarrow
	•	Transmission bolts	✓
Gear stick souta <u>ਿੱ</u> Electricity system C	heck points: 15 Note 0	Transmission boits	
<u> </u>	heck points: 15 Note 0 OK Note N/A		OK Note N/A
हिन्दे Electricity system C	heck points: 15 Note 0	Car error codes	
हिंदी Electricity system C	heck points: 15 Note 0 OK Note N/A		OK Note N/A
ि Electricity system C Battery Alternator	heck points: 15 Note 0 OK Note N/A	Car error codes	OK Note N/A
<u> </u>	heck points: 15 Note 0 OK Note N/A	Car error codes A/C condenser	OK Note N/A
Electricity system Constitution	heck points: 15 Note 0 OK Note N/A	Car error codes A/C condenser A/C radiator	OK Note N/A
Electricity system Constitution	heck points: 15 Note 0 OK Note N/A	Car error codes A/C condenser A/C radiator A/C filter	OK Note N/A
Electricity system Constitution	heck points: 15 Note 0 OK Note N/A	Car error codes A/C condenser A/C radiator A/C filter A/C hose	OK Note N/A



% liquids	Check points: 6 Notes: 0				
liquius	check points: O Notes.				
	OK Note N/A		ОК	Note	N/A
Engine oil	✓	Engine coolant	✓		
Transmission oil	✓	Windshield Fluid	✓		
Brake fluid	✓	Steering Fluid	✓		
Under the car	Check points: 8 Notes: 1				
	OK Note N/A		ОК	Note	N/A
Idler arm	✓	Cross member sub assy			✓
Steering hoses	✓	Inner tyre rod end			✓
Steering box	✓	Outer tyre rod end			✓
Rack and pinion steering	✓	Ball joint right			✓
Rear shock absorbers	✓	Ball joint left			✓
Front shock absorbers	✓	Top strut mount			✓
Upper arm bushing	✓	Front stabilizer linkage			~
Rear lower arm bushing	✓	Rear stabilizer linkage			✓
Suspension spring	✓	Rust			
Stabilizer link rubber	✓	exhaust	✓		
Stabilizer link	✓	Under the vehicle	✓		
Break System	Check points: 15 Notes: 1				
	OK Note N/A		ОК	Note	N/A
Brake master CLY	✓	Wheel bearing rear	✓		
Vacuum brake booster	✓	Wheel bearing front rear	~		
Brake hoses	✓	Brake wheel cylinder front left	✓		
Brake hoses Brake pad front	✓ ✓	Brake wheel cylinder front left Brake wheel cylinder front right	✓ ✓		
Brake pad front	✓	Brake wheel cylinder front right Brake wheel cylinder rear left Brake wheel cylinder rear right	\rightarrow \right		
Brake pad front Brake pad rear	>	Brake wheel cylinder front right Brake wheel cylinder rear left	✓ ✓		



	OK Note N/A		OK Note	N/A
Control panel Switch	✓	Right front seat	✓	
Lock button	✓	Back mattresses	✓	
Accessories	✓	Roof mat	✓	
Mirror control switch	✓	Right front door decoration	✓	
Dashboard	✓	Front door left decoration	✓	
Drive wheel buttons	✓	Back door right decoration	✓	
Display	✓	Back door left decoration	✓	
Drive wheel	✓	The left front window button	✓	
Speakers	✓	The left rear window button	✓	
Roof	✓	The right rear glass button	✓	
Air condition vents	✓	The left rear glass button	✓	
A/C control	✓	Gear shift	✓	
Sun Roof	✓	Cup holder	✓	
	✓	Trunk opening button	✓	
Sun visor right	Check points: 11 Notes: 0	Trunk opening button Hood button	~	
Sun visor right Left front seat	✓ ✓	·		N/A
Sun visor right Left front seat Additional	Check points: 11 Notes: 0	·	~	N/A
Sun visor right Left front seat Additional Console	Check points: 11 Notes: 0 OK Note N/A	Hood button	~	
Sun visor right Left front seat Additional Console Folding mirrors	Check points: 11 Notes: 0 OK Note N/A	Hood button Back screens	OK Note	
Sun visor right Left front seat Additional Console Folding mirrors Tool bag	Check points: 11 Notes: 0 OK Note N/A	Hood button Back screens Lipper doors	OK Note	~
Sun visor right Left front seat Additional Console Folding mirrors Tool bag	Check points: 11 Notes: 0 OK Note N/A	Hood button Back screens Lipper doors Rear brake assist	OK Note	
Sun visor right Left front seat Console Folding mirrors Tool bag Crane	Check points: 11 Notes: 0 OK Note N/A	Back screens Lipper doors Rear brake assist Front brake assist	OK Note	
Sun visor right Left front seat Console Folding mirrors Tool bag Crane Safety triangle	Check points: 11 Notes: 0 OK Note N/A	Back screens Lipper doors Rear brake assist Front brake assist Remote engine start 4W button	OK Note	
Sun visor right Left front seat Console Folding mirrors Tool bag Crane Safety triangle Camera	Check points: 11 Notes: 0 OK Note N/A	Back screens Lipper doors Rear brake assist Front brake assist Remote engine start 4W button Hood suspension	OK Note	✓ ✓
Console Folding mirrors Tool bag Crane Safety triangle Camera Cruise control	Check points: 11 Notes: 0 OK Note N/A	Back screens Lipper doors Rear brake assist Front brake assist Remote engine start 4W button	OK Note	



Exterior CI	neck points: 29 Notes: 3		
	OK Note N/A		OK Note N/A
Front Section (Overall)	✓	Right front fender	✓
Front bumper condition	✓	Right rear fender	✓
Headlights & indicators	✓	Side mirror (right)	✓
Bonnet condition	✓	Door pillar / structural alignment (right)	✓
Front grill(s)	✓	Back Side (Overall)	✓
Front windscreen (chips, cracks, seals)	✓	Rear bumper	✓
_eft Side (Overall)	✓	Boot / tailgate condition	
Front left door		Rear windscreen (glass & seals)	✓
Rear left door		Tail lights	✓
_eft front fender	✓	Rear garnish / trims	✓
_eft rear fender	✓	Roof (Overall)	✓
Side mirror (left)	✓	Roof condition (paint, dents, scratches, rust)	✓
Door pillar / structural alignment (left)	✓	Roof accessories (if any, e.g. rails, sunroof cond	dition/seals)
Right Side (Overall)	✓	·	
Front right door	✓		
Rear right door	✓		



List of Notes (Issues Found)

Under the vehicle Note:

Rear lower arm bushing photo Rear lower arm bushing note

Ball joint left photo Ball joint left note

Rust photo





Rust note

minor surface rust building

Break System Note:

Rear brake disc rotor note



Wheel bearing front photo



wheel bearing suspected for mild hum, though cannot be confirmed without a lifting test.

Wheel bearing front note

Tyre

Note:

ī.

Same Brand, Size, Style photo



Same Brand, Size, Style note

oversized true installed



Exterior Note: 3

Front bumper condition photo Front bumper condition note


Front left door photo



painted, no sign of accident found

Front left door note

Rear left door photo



painted, no sign of accident found

Rear left door note



Boot / tailgate condition photo





Boot / tailgate condition note

The tailgate doesn't open, and tailgate window hinges are broken.



Exterior Photos




Multi Photo


















































Interior Photos



Multi Photo












































How to read the inspection report

The inspection is carried out by a specialized car inspector from a car company, where the inspector inspects the car in several stages:

All checkpoints have more than one status:

- 1. Body: The inspector inspects all parts of the body and identifies damage to each part of the car, such as: the front fender, the rear, Windscreen, Windows, Bumpers, and Mirrors.
- 2. Electrical system: This involves checking the car's electrical parts and ensuring they are working properly, such as: the battery and the wiring.

3. Car mechanics: It is divided into several main sections, which are:

* Engine: Checking the parts related to the engine's operation, such as the air filter and engine cover. Gearbox: Checking the proper operation of the car's transmission mechanism, such as the gear cooler sand gearbox face.

* Brake system: It includes the basic points of the brake system, such as: rear hub, front brakes.

- * Differential and Corona: It is the part responsible for the balance and stability of the car, including the supports, such as: the propeller shaft, and the front reverse.
- * Under the car: Parts and components located under the car that can only be accessed from under the car, such as: chassis arm, stabilizer bar.
- * Fluids: Check the condition of essential fluids in the car, such as: engine oil, gearbox oil.
- 4. Interior: Check the car's interior for damageable parts and decorations, such as: window controls and steering wheel.

All checkpoints have more than one status:

- 1. In good condition: This means that the point has been checked and is working well or has no apparent damage.
- 2. Note: This means that there is damage or it is not working properly. A picture of each note is attached at the end of the report.Edit this text

Disclaimer

This pre-purchase vehicle inspection has been carried out by a CarAssure Inspector to provide an independent visual assessment of the vehicle's condition at the time and location of inspection. The inspection is non-invasive and based solely on what is visibly accessible and operable during the inspection process.

The inspection does not include dismantling, removing, or testing internal components of the engine, gearbox, transmission, or other mechanical and electrical systems. It may not identify intermittent faults, hidden issues, or defects that appear only under specific conditions such as high-speed driving, temperature changes, or future use.

The inspection does not include checks for rust, corrosion, flood or water damage, previous accident repairs, or cosmetic paintwork beyond what is visible at the time of assessment.

No coolant pressure test, compression test, or diagnostic scanning is performed unless explicitly stated.

This report is not a Certificate of Roadworthiness or Safety Certificate (RWC) and should not be relied upon as proof of the vehicle's roadworthiness, compliance, or fitness for registration.

The findings and opinions presented in this report represent the professional judgment of the CarAssure Inspector and are provided for informational purposes only. The final decision to purchase or reject the vehicle remains the sole responsibility of the buyer.

CarAssure provides no guarantee or warranty that this inspection will identify every defect or prevent future mechanical or electrical failure.

CarAssure and its inspectors accept no liability or responsibility for any issues, damages, losses, or costs arising after the inspection or following the purchase of the vehicle.